Oakland Plantation, Smokehouse Intersection of Routes 428 and 429 Odessa vicinity New Castle county St. Georges Hundred Delaware HABS NO. DE-246-A
HABS
DEL,
2-00.V,
5-

WRITTEN HISTORICAL AND DESCRIPTIVE DATA
REDUCED COPIES OF MEASURED DRAWINGS

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, DC 20013-7127

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE



ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINI	TY
DELAWARE	NEW CASTLE		ODESSA VICINITY	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.
OAKLAND PLANTATION, SMOKEHOUSE				DE-246-A
SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
Intersection of Routes 428 and 429, west of Odessa, St. Georges Hundred				
DATE OF CONSTRUCTION (INCLUDE SO circa 1842	ARCHITECT(S) (INCLUDE SOURCE)			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
Oakland smokehouse is a good example of a multi-functional outbuilding like those proposed by reform-oriented farmers of the mid-nineteenth century.				
de la constant de la				
STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)				
Walls below grade are rubble fieldstone; those above are brick.				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
Two level with a fully finished root cellar; vaulted ceiling in cellar; original icehouse addition on southeast gable end destroyed; exterior covered stair				
EXTERIOR FEATURES OF NOTE				
Evidence of original icehouse addition on southeast gable end, including ground depressions impressions of boards in cement and continuation of brick wall at lower right corner.				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
PRESENT CONDITION AND USE				
Good condition but extensive brick deterioration due to spalling on southeast gable end, resulting in partial and completely missing bricks in large areas.				
OTHER INFORMATION AS APPROPRIATE				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
ational Register of Historic Places				
COMPILER, AFFILIATION Margaret	· · · · · · · · · · · · · · · · · · ·			E 3/86
Architecture and Engineering, University of Delaware 5/23/86				